



**Fairmont Hot Springs
Utilities Ltd.**

October 23, 2025

UPDATE ON WATERLINE BREAK

Water break has been located and isolated. Upper Fairmont area east and north of Mountainside Golf course should have water pressure restored. The watermain east of Mountainside golf course is closed. All areas, south and east of Mountainside golf course will continue to experience a service disruption while the repair crew repair the water line. This is a major waterline break. Estimated time of repair and water service restoration to the affected areas in 4:00pm MST, October 23, 2025.

Kind regards,

FAIRMONT HOT SPRINGS UTILITIES

5255 Fairmont Resort Road, Fairmont Hot Springs, BC V0B 1L1